



## Follow-up Service Inspection Report E2253501210826162523

INSPECTION DETAILS			
Date:	2021-08-26	File Number.:	E225350
Responsible Office:	Melville	Volume:	1
Inspection Center:	221	CCN:	QMMY2
Product Type:	Fabricated Parts	UL Rep Name:	Alvin Richardson
Deliverable Type:	Recognized	UL Rep ID:	22927
Party Site Number:	603704	Subscriber Factory No.:	332093-001
Manufacturer Name:	TSP INC	Factory Rep Name	Ms. Lori Tigert
Manufacturer Address:	2009 Glenn Pkwy Batavia, OH 45103-1676	Factory Rep Phone:	513-732-8900, 108
		Factory Rep Email:	ltigert@tspinc.com
Nature of visit:	Regular Inspection	Sample Status:	Samples not required
UL Marks Used?	Yes	UL Marks Removed?	No
Variation Notice Issued?	No	Inspection Conducted Remotely?	Yes
Comments After Submission:			

PRODUCT DOCUMENTS/PRODUCTION READY VISIT			
Model	Product	Section	Multiple Listed
A1884	Fabricated Parts	1	No

SAMPLE DOCUMENTS			
If samples are required to be sent to UL, indicate below. If required samples are not sent, explain in the Comments area.			
No Samples			
Additional Comments			

In addition to the requirements specified in the applicable UL Services agreement and Follow-Up Service Procedure, UL further defines responsibilities, duties and requirements for both manufacturers and UL representatives in the document titled "UL Mark Surveillance Requirements" that can be located at [www.ul.com/fus](http://www.ul.com/fus), and in accordance with the applicable terms and conditions of the document at [www.ul.com/responsibilities](http://www.ul.com/responsibilities). Manufacturers without Internet access may obtain the current versions of these documents from their local UL customer service representative or UL field representative.